

Vertex Standard

CN_VX-9_VX-1400_2017_04

CANCELLATION NOTE

Product group affected:

Vertex Standard

Overview:

The following radios are being discontinued.

Parts Being Cancelled:

AC033N015-VSL VX-921E-D0-5 C EU (CE) 136-174 MHZ AC033U019-VSL VX-921E-G6-5 A EU (CE) 400-470 MHz AC033N016-VSL VX-924E-D0-5 C EU (CE) 134-174 MHz AC033U020-VSL VX-924E-G6-5 A EU (CE) 400-470 MHz AC075L001-VSL VX-925E-B4-5 (CE) 66-88 FUG13B AC075N001-VSL VX-925E-D0-1 C (CE) 134-174 FUG11B AC075N002-VSL VX-925E-D0-5 (CE) 134-174 FUG10B AC033N017-VSL VX-929E-D0-5 C EU (CE) 136-174MHz AC033U021-VSL VX-929E-G6-5 A EU (CE) 400-470 MHz

AC091H002-VSL 30 M

VX-1400-SA0B-100 RX: 30 kHz-30 MHz; TX: 1.6-

30 MHz

AAG62X001 RMK-1400 IP54 REMOTE KIT VX-1400

AAG64X001 AUTO LINK ESTABLISHMENT 2 VX-1400

AAG86X001 MMB-92 MOUNTING BRACKET FOR VX-1400

Effective date:

Last Order Date: 30.06.2017

Replacement Parts:

VX-1700 (for VX-1400)

Further information:

Please contact your Vertex Standard sales representative or Customer Support Manager for further information.

Motorola Document Classification MGBI: External Channel Partners

April 2017 page 1 of 1

Whilst care has been taken to ensure the accuracy of the information contained in this bulletin, Motorola Solutions retains the right to make changes at any time without notice.

Motorola, Moto, Motorola Solutions and the Stylized M Logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC and are used under license. All other trademarks are the property of their respective owners. © 2017 Motorola Solutions, Inc. All rights reserved.